


DOT Parking head-on



1. North end of trailer interior sheet rock needs to be removed.
2. Check for condensation build up from air con unit.
3. Replace sheet rock, spackle, and paint.