

DLNR Job #: 26-SPO-016

Site Pictures

Site Area: Pavilion #3


Pavilion roofing

Pavilion roofing



Corroded bracket and hardware example

Concrete spall and corroded bracket example



DLNR Job #: 26-SPO-016

Site Pictures

Site Area: Pavilion #3

Concrete spall and corroded bracket example



Concrete spall and corroded bracket example

Corroded bracket example



Concrete spall and corroded bracket example



Keiwa Heiau State Recreation Area Comfort Stations General Repairs and Reroof

DLNR Job #: 26-SPO-016

Site Pictures

Site Area: Pavilion #3

Concrete spall and corroded bracket example



Concrete spall example

Exterior



Concrete spall and corroded bracket example



Keiwa Heiau State Recreation Area Comfort Stations General Repairs and Reroof

DLNR Job #: 26-SPO-016

Site Pictures

Site Area: Pavilion #3

Rotting roof decking example



Roof decking

Wood rot example



Exterior



Scope of Work

