Kinau Hale, 1250 Punchbowl Street - Safety Repairs

Background

Minor safety repairs are required throughout the building.

Scope of Work

To address these repairs, we request a proposal for the following work, complete and in-place:

- 1. Basement:
 - a. Replace drainline in OHSM vault.
 - b. Replace water line in HISO #2.
- 2. First Floor:
 - a. Paint and reseal exterior Vault walls.
 - b. Address exterior wall leaks on Ewa-Makai side of building.
 - c. Replace/add exterior floor tiles on Makai entry.
 - d. Remove 4 abandoned AC units on Makai side and patch walls as necessary.
 - e. Framing and installation of a partial wall and door in Room 123 and removal of a half-wall.
- 3. Second Floor:
 - a. Encapsulate existing plaster ceiling.
 - b. Replace drainline in conference room on Makai-Diamond Head side.
- 4. Third Floor:
 - a. Encapsulate existing plaster ceiling.
 - b. Address leaks in Men's Restroom and Director's Office
- 5. Fourth Floor:
 - a. Provide catchment for two floor drains adjacent to refrigerators.
 - b. Remove abandoned drainline and cap at ceiling in Room 447.
 - c. Encapsulate existing plaster ceiling.
- 6. All floors: Replace fire hoses.

Time of Performance

180 days from a written notice to proceed.

Invoicing

Contractor shall submit an original invoice, which includes the Contract Number to:

Department of Accounting and General Services Central Services Division 729 Kakoi Street Honolulu, Hawaii 96819 Attn: Teri Wong

<u>Final Payment Requirements.</u> Contractors are required to submit a "Certificate of Vendor Compliance" for final payment on the contract. Hawaii Compliance Express Certificates of Compliance satisfies this requirement. https://vendors.ehawaii.gov/hce

End

Attached Plans