

**Table 1: Asbestos Sampling Results  
Foreign-Trade Zone No. 9 (continued)**

Sample Number	Location	Sample Description	Condition			Asbestos % and Type	Asbestos Containing?
			% Damaged	Extent of Damage	Type of Damage		
2002-0217-157	Second floor deck, south side, on FC 2-15	Black vibration cloth	2-5	Localized	Physical	None Detected	No
2002-0217-158	Second floor deck, south side, on FC #14	Black vibration cloth	2-5	Localized	Physical	None Detected	No
2002-0217-159	Second floor deck, south side, on FC #13, east side	Black vibration cloth	2-5	Localized	Physical	None Detected	No
2002-0217-160	Second floor deck, south side, on FC #13, west side	Black vibration cloth	2-5	Localized	Physical	None Detected	No
2002-0217-161	Second floor deck, south side, on unit west of FC #13	Black vibration cloth	2-5	Localized	Physical	None Detected	No
2002-0217-162	Second floor deck, south side, on unit for room 225	Black vibration cloth	2-5	Localized	Physical	None Detected	No
2002-0217-163	Second floor deck, south side, on unit for room 227	Black vibration cloth	2-5	Localized	Physical	None Detected	No
2002-0217-164	Southeast corner of warehouse	Black asphalt flooring	10	Distributed	Physical	None Detected	No
2002-0217-165	East side of warehouse, middle	Black asphalt flooring	10	Distributed	Physical	5% Chrysotile	Yes
2002-0217-166	East side of warehouse, middle	Black asphalt flooring	10	Distributed	Physical	5% Chrysotile	Yes
2002-0217-167	Northeast corner	Black asphalt flooring	10	Distributed	Physical	3% Chrysotile	Yes
2002-0217-168	Middle of warehouse, north side	Black asphalt flooring	10	Distributed	Physical	None Detected	No
2002-0217-169	Middle of warehouse, north side	Black asphalt flooring	10	Distributed	Physical	5% Chrysotile	Yes
2002-0217-170	Middle of warehouse, north side	Black asphalt flooring	10	Distributed	Physical	2% Chrysotile	Yes
2002-0217-171	Middle of warehouse, south side	Black asphalt flooring	10	Distributed	Physical	None Detected	No
2002-0217-172	Southwest corner of warehouse	Black asphalt flooring	10	Distributed	Physical	None Detected	No
2002-0217-173	West side of warehouse, middle	Black asphalt flooring	10	Distributed	Physical	5% Chrysotile	Yes
2002-0217-174	West side of warehouse, middle	Black asphalt flooring	10	Distributed	Physical	None Detected	No
2002-0217-175	Northwest corner of warehouse	Black asphalt flooring	10	Distributed	Physical	None Detected	No

- Materials containing greater than 1% of asbestos mineral fibers are considered to be asbestos-containing materials as defined by the National Emission Standards for Hazardous Air Pollutants (NESHAP) regulation (40 CFR 61).