

FIRE EQUIPMENT INSPECTION AND SERVICE REPORT

Hydrant Location	Latitude	Longitude	Altitude	Static Pressure	Residual Pressure	Pitot	Flow Rate GPM	@ 20 psi Residual	Comments
Diamond Head crater									
Portable trailers	21.1550	157.4820	290	70	25	7	217	230	1.75 insert. Need to investigate low pressure
Parking lot	21.1549	157.4817	300	75	50	39	513	540	
Building 4204 Diamond head rd	21.1549	157.4812	300	50	15	6	201	185	1.75 insert. Need to investigate low pressure

Comments:

_____/s/ Sam Smith_____	FPS-HFD-2023-008	7/27/2023
Signature of Inspector	License Number	Date