



# 2024

## North Kohala Library


54-3645 Akoni Pule Hwy  
Kapaau, HI 96755  
808-889-6655

**Building Contact:** Matthew Kaip  
**Title:** Site Contact

**Company:** Guardian Fire, LLC  
**Contact:** Jared David-Chapman  
**Title:** Inspector

**Inspection Date: Dec 19, 2024**

This Inspection was performed in accordance with applicable Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.



# EXECUTIVE SUMMARY

Generated by: BuildingReports.com

## Building Information

<b>North Kohala Library</b> 54-3645 Akoni Pule Hwy Kapaau, HI 96755 United States of America	<b>Contact:</b> Matthew Kaip
	<b>Phone:</b> 808-889-6655
	<b>Fax:</b>
	<b>Mobile:</b>
	<b>Email:</b> facilities@librarieshawaii.org

## Inspection Performed By

<b>Guardian Fire, LLC</b> 73-5577 KAUHOLA ST KAILUA KONA, HI 96740-2642 United States of America	<b>Inspector:</b> Jared David-Chapman
	<b>Phone:</b> 808-896-4515
	<b>Fax:</b>
	<b>Mobile:</b>
	<b>Email:</b> jared@gfhawaii.com


## Inspection Summary

Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Fire	2	100.00%	2	100.00%	2	100.00%	0	0.00%
<b>Totals</b>	<b>2</b>	<b>100%</b>	<b>2</b>	<b>100.00%</b>	<b>2</b>	<b>100.00%</b>	<b>0</b>	<b>0.00%</b>

## Certification

**Company:** Guardian Fire, LLC


**Inspector:** Jared David-Chapman



**Signed:** Dec 19, 2024

**Building:** North Kohala Library

**Contact:** Matthew Kaip



**Signed:** Dec 19, 2024

# INSPECTION & TESTING

Generated by: [BuildingReports.com](https://BuildingReports.com)

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other . Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

**Building:** North Kohala Library

Device Type	Location	ScanID : S/N	Service	Time	Date
<b>PASSED</b>					
<b>Fire</b>					
Fire Extinguisher, 10 Lbs, A.B.C.	Back door	B04832462	Annual Service	2:17:55 PM	12/19/24
Fire Extinguisher, 10 Lbs, A.B.C.	Outside front door	B04832057	Annual Service	2:14:43 PM	12/19/24

# SERVICE SUMMARY

Generated by: BuildingReports.com

The Service Summary section provides an overview of the services performed in this report.

**Building:** North Kohala Library

Device Type	Service	Quantity
<b>PASSED</b>		
Fire Extinguisher, A.B.C., 10 Lbs	Annual Service	2
<b>Total</b>		<b>2</b>
<b>Grand Total</b>		<b>2</b>

# INVENTORY & WARRANTY REPORT

Generated by: [BuildingReports.com](https://BuildingReports.com)

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

**Building:** North Kohala Library

Device or Type	Category	% of Inventory	Quantity
Fire Extinguisher	Fire	100.00%	2

Type	Qty	Model #	Description	Manufacture Date
------	-----	---------	-------------	------------------

## IN SERVICE - 5 YEARS TO 10 YEARS

### Amerex

Fire Extinguisher	2		A.B.C.	12/19/2015
-------------------	---	--	--------	------------