Kalopa, Cabin Flooring & Painting

DLNR Job #: 26-SPH-001

Site Pictures

Site Area:

Cabin 1B
Repair subfloor in kind.

Cabin2A

Cabin 2A
Remove and replace interior VCT in bathrooms and main cabin area with sheet vinyl. Install ADA compliant transitions where needed. Add Alt. #1 Paint interior areas to match existing.

Cabin 2A