DLNR Job #: 26-SPO-016

Site Pictures

Site Area: Comfort Station #3

Exterior

Exterior

Exterior

Spalling concrete

DLNR Job #: 26-SPO-016

Site Pictures

Site Area: Comfort Station #3

Siding patches

Damaged siding

Security gate

Concrete caps missing